

	Full Council
Date	11 August 2025
Agenda Item	7e

Rubber speed bump in Chapel Street carpark

A request has been received from Sainsburys for HTC to repair the rubber speedbump in Chapel Street carpark. This is currently a system of bolts and rubber which is constantly falling apart. Sainsburys were consulted about replacing it with a tarmac speed bump, as this would last, and they agreed. Quotes have been sought from 5 contractors. At present only one quote has been received after a wait of 3 weeks. This is from a contractor who has previously done work for the Council satisfactorily. As the matter is relatively urgent, since the broken current speedbump can cause damage to tyres, it is suggested that this quote might be accepted.

Quote 1: £930 + VAT

Recommendation : that HTC accepts quote 1, to be paid out of the budget for car park maintenance.



Sarah Greateorex Town Clerk